

RISK ASSESMENT

| Risk | Use of Walkers Outdoors | Prepared by: | H&S Co-ordinator – S.L & V.D |
|------------|-------------------------------------|--------------------|------------------------------|
| Assessment | | Assessed by SLT: | |
| for: | | , | |
| Location: | ROSEWOOD FREE SCHOOL & AVENUES SITE | Date of Assessment | January 2023 |
| | | Review Date: | January 2025 |

| Hazard | Who might be harmed? | Hazards Identified which may cause harm – consequence | Existing Level of Risk | Control Measure and Precautions Taken | Additional Control Measures or Further Action Required | Remaining level of Risk |
|--|-------------------------|---|---------------------------|--|--|----------------------------|
| Suitable walker for outside | Employees & Learners | Equipment failure. Walker tipping and cause learner to fall out of walker causing varying musculoskeletal & impact injuries. | Medium - 10 | Following manufactory guidelines of individual walker. Walker never to be stored outside. Clean equipment after outdoor use for indoor use. | Annual maintenance checks by OT. | Low - 5 |
| Suitable learner for outside walking | Employees & Learners | Impact injury causing bumps and bruising. | Low - 6 | Only experienced walker that can tolerate different walking surfaces. Refer to behaviour plan if applicable. Suitable footwear. 1-1 ratio outside. | | Low - 3 |
| Suitable adult for outside walking | Employees & Learners | Muscular skeletal & other physical injuries | Medium - 10 | Experienced staff member who knows how to alert for help in an emergency. Suitable protective footwear. 1-1 ratio outside. Follow guidance for walking inside school. Follow M&H training for posture and positioning. | | Low - 5 |
| Weather conditions | Employees & Learners | Poor weather causing slips, trips or falls. | Medium - 9 | Walker not to be used when the flooring surface is excessively wet or has ice or snow on it. | | Low - 3 |
| Door threshold | Employees & Learners | Trips and falls over the threshold causing bumps and bruising. Muscular skeletal injury. | Medium - 9 | Ensure doorway threshold is flat for smooth exit and entrance. | Inform M&H if any concerns | Low - 3 |



RISK ASSESMENT

| Hazard | Who might be harmed? | Hazards Identified which may cause harm – consequence | Existing Level of Risk | Control Measure and Precautions Taken | Additional Control Measures or Further Action Required | Remaining level of Risk |
|---|----------------------|---|---------------------------|--|--|----------------------------|
| Door frames | Learners | Bump into/on the doorway as it is an enclosed space causing damage to backs, neck, shoulders feet and hips. Impact injury causing bruising or cuts | Medium - 9 | Ensure door is positioned or temporally held open/back to allow clear exit as to not bump into somebody or frame. Staff mindful of pupil's limbs and individual movements. | | Low - 3 |
| Flooring | Learners | Walker tipping and cause learner to fall out of walker causing varying musculoskeletal & impact injuries. | Medium - 10 | Walkers on smooth even flat surfaces only Ensure flooring is clear of hazards i.e., wet leaves, prior to going for a walk. Good housekeeping and flooring maintained. | | Low - 5 |
| Outdoor obstacles | Learners | Impact injury and falls. | Low - 6 | Stay out of the swing and roundabout yellow zone. Avoid open windows. Be vigilant with mobile, independent learners and play equipment. Good housekeeping and flooring cleared. | | Low - 3 |
| Re-entering the class during poor weather | Staff & Learners | Walker leaving wet floor causing slips, trips or falls or loss of control of walker. Broken limbs, muscular skeletal & other physical injuries. | Medium - 10 | Ensure there is a mat to dry off / clean feet & walker wheels during poor weather. | | Low - 5 |
| Malfunction of Rose Road lift | Staff & Learners | Use of walker in lift and failure of lift causing prolonged length of time in stander in turn possible damage to body. Confined space causing impact injuries and possible behaviour changes. | Medium - 10 | No use of walkers in the lift. | | 0 |
| High likelihood of risk – Likely to occur immediately or in the near future Medium likelihood of risk – will occur in time if no preventative action is taken Low likelihood of risk – Remote or unlikely to occur | | | | | | |



RISK ASSESMENT

| Date Reviewed | Comments |
|---------------|--------------------------------------|
| January 2021 | Initial assessment |
| January 2022 | Annual update. Added on use of lift. |
| January 2023 | Annual update |