



RISK ASSESSMENT

Risk Assessment for:	CEILING XY/SINGLE TRACK HOIST	Prepared by	M&H TRAINERS – S.L & V.M
		Assessed by SLT:	
Location:	ROSEWOOD FREE SCHOOL & AVENUES SITE	Date of Assessment	May 2022
		Review Date:	May 2024

Hazard	Who might be harmed?	Hazards Identified which may cause harm – consequence	Existing Level of Risk	Control Measure and Precautions Taken	Additional Control Measures or Further Action Required	Remaining level of Risk
Hoist not charged or failing mid hoist	Employees, M&H trained third party	Hoist being out of action increasing time, space and pressure on the use of the other hoist or the need for use of Mobile hoist leading to increased work load and stress for staff plus possible musculoskeletal injuries if mobile hoist required.	Med-9	<p>All hoists are to be placed on charge after each use.</p> <p>All hoists are regularly serviced and maintained.</p> <p>All staff are trained on use of the hoist during Moving and Handling induction and have yearly refresher training.</p> <p>Moving and Handling Trainers on site to assist with safety of staff and Learner should issues arise during hoisting.</p> <p>Staff will never use a Hoist which appears to be faulty or has signs of damage/ loss of charge/low battery.</p> <p>Each class has two hoists so second hoist should be used if 1 fails to avoid use of mobile hoist. If mobile hoist required liaise with M&H prior to use.</p> <p>Emergency lowering system can be used – staff trained.</p>	<p>Report faults to M & H Team.</p> <p>Contact service contractor where appropriate.</p> <p>Staff to have read all supporting documents and learner handling plans. Refer to emergency situation protocol.</p>	Low-3

RISK ASSESSMENT

Hazard	Who might be harmed?	Hazards Identified which may cause harm – consequence	Existing Level of Risk	Control Measure and Precautions Taken	Additional Control Measures or Further Action Required	Remaining level of Risk
Hoist not being charged or failing mid hoist	Learner	Discomfort/injury due to faulty hoist e.g. stops working midway through manoeuvre, Learner is active in sling and may fall out causing impact injury, cuts, bruise, head injury	Med-10	As above page 1 All Learners have own sling assessed for them for comfort and safety eg use of waist band should the hoisting take longer than expected Staff to follow Learners Moving and Handling plan at all times.	As above page 1	Low-5
Hoisting Manoeuvre	Employee M&H trained third party	Musculoskeletal injury whilst supporting Learners through hoisting manoeuvre due to bad posture, inadequate training or information	Med-10	Staff receive Moving and Handling induction training prior to undertaking hoisting with our Learners, plus a yearly refresher. All staff to read and follow each Learners Individual Moving and Handling Risk assessment. Staff have individual risk assessments to match their current physical needs. Classrooms to be free of clutter and obstacles to minimise risk of slips/trips during Hoisting All current slings are compatible with school overhead hoist systems. No Learner in school exceeds the safe working load. All equipment should be ready to receive the Learner. Rosewood operates on a lead hoister (a “first”) and a “second” to ensure less experienced staff member is well supported and instructed.		Low-5

RISK ASSESSMENT

Hazard	Who might be harmed?	Hazards Identified which may cause harm – consequence	Existing Level of Risk	Control Measure and Precautions Taken	Additional Control Measures or Further Action Required	Remaining level of Risk
Hoisting Manoeuvre	Learner	Discomfort from poorly fitted sling or injury from falling out of sling due to wrong loops attached, sling fitted incorrectly, wrong sling used, hoist used incorrectly	Med-15	<p>Staff receive Moving and Handling induction training prior to undertaking hoisting with our Learners, plus a yearly refresher.</p> <p>All staff to read and follow each Learners Individual Moving and Handling Risk assessment.</p> <p>All Learners have own sling assessed for them for comfort and safety eg use of waist band should the hoisting take longer than expected</p> <p>All Handling plans carefully specify how many trained people are required for each hoist to keep the Learner safe.</p> <p>Rosewood operates on a lead hoister (a “first”) and a “second” to ensure each learner has one competent and known staff member with them for hoisting</p> <p>Learners should not use the hoist hand set.</p>	Refer to quick guide- the A5 for relevant hoisting information. One on each Learners chair with photo of sling, loops to use and information on Learners movements and other important information for each hoist	Low-5

RISK ASSESSMENT

Hazard	Who might be harmed?	Hazards Identified which may cause harm – consequence	Existing Level of Risk	Control Measure and Precautions Taken	Additional Control Measures or Further Action Required	Remaining level of Risk
Spreader bar during & after hoisting	Employees, Learners, third parties	The spreader bar on the hoist could move and hit employees learners or third parties and could cause varying injuries including impact injuries to head or face, bruising and cuts.	Med-9	All hoisting in school is to be completed with a minimum of 2 people or with the number the risk assessment states. Staff follow the Learners Risk Assessment at all times. We work with a clear 'leader' and 'second' during hoisting to ensure that one staff member is always responsible for the spreader bar. All overhead hoists are stored to above head height immediately after each hoist is complete or short term over a suitable table so as to prevent staff from hitting themselves on a low hoist. Then placed on charge when all manoeuvres are completed.	All staff read and follow Learner Risk assessments Accident/ incident book monitored	Low-3
Attaching sling to hoist	Employees, Learners, third parties	The learners sling loops may slip off the spreader bar and pupil may strain or bump limbs or head or fall from sling. Staff – may catch learner therefore injuring themselves - musculoskeletal injury	Med -10	Staff receive Moving and Handling induction training prior to undertaking hoisting with our Learners, plus a yearly refresher. At least 2 adults present for manoeuvre. Use safety clips provided on the hoists.	Service of hoists. Team to communicate if clips are damaged	Low-5

RISK ASSESSMENT

Hazard	Who might be harmed?	Hazards Identified which may cause harm – consequence	Existing Level of Risk	Control Measure and Precautions Taken	Additional Control Measures or Further Action Required	Remaining level of Risk
Fitting sling to to Learner	As above	Learner may fall out of sling causing varying injuries. Adult – may catch learner therefore injuring themselves - musculoskeletal injury	Med-10	Each Learner has their own personal sling with designated loops. Learners \Risk Assessments and A5 cards to risk assessments to support this. Learners only to use their own sling other than in an emergency when the M&H team will support manoeuvre. Slings are checked visually for condition before use each time. Travelling with pupils keep to a minimum. Staff receive Moving and Handling induction training prior to undertaking hoisting with our Learners, plus a yearly refresher. At least 2 adults present for manoeuvre. Almost every Learner arrives in school sitting on their sling	Learners referred to OT sling clinics when required - Class to inform OT's if a sling is becoming too small or a change in the Learners movements.	Low-5
<p>High likelihood of risk – Likely to occur immediately or in the near future Medium likelihood of risk – will occur in time if no preventative action is taken Low likelihood of risk – Remote or unlikely to occur</p>						

Date Reviewed	Comments
April 2017	Initial assessment
April 2018	Annual update
April 2019	Annual update
April 2020	Annual update
May 2022	Two yearly update